Ez-link installation and uploading of .sf program files into an indicator from the PC

- 1. Install Ez-link on a PC or laptop computer. A folder will be created on the drive named Ezlink that contains the entire application file to run Ezlink. You can create a shortcut on your desktop with the target file being Ezlink.exe located in this folder.
- 2. Copy any program files from installation zip file with the extension .sf to this directory. Some example programs are included with the software.
- 3. Uploading a program into the indicator: Open ezlink.exe and the application will start.

| 💳 EZ Link | | | | | _ 8 × |
|--|--|--|--|---|-------|
| File Utilities Help | com () | | | | |
| | | | | | |
| | | | | | |
| Lipload file to | Configure - | | | X | |
| opioad me to indicator. Click On this button | Scale I/O Ports Miscelaneous Print Formats Print Labels Application Description | Fixed Registers Keyboard Events Setpoint Events Timer Events Scale Basic | Passwords Display List Reset to Defaults Help | | |
| | | | | | |

Document1 - Microsoft W... 🔯 C:\BC5

🏵 😼 📶 🚵

📸 1:10 PM

EZ Link

🏽 Start 🛛 🔼 🔟 🏉 🗐 🖳 🎱 🗹 🔍 🐨

| | | | Com Err 0 | NUM |
|---------------------------|---------|-------------------------|-----------|---------------------|
| 🏽 Start 🔢 📶 🏉 🗐 🔛 🎱 🗹 🖄 🐨 | EZ Link | Document1 - Microsoft W | 🔍 C:\BC5 | 🛞 🛃 📶 🚵 📯 % 1:13 РМ |



] [**g**t Start] | 🔼 🎾 🏈 😂

The upload window will appear containing the path for the program file that was selected. With the indicator turned on and in idle mode (not CFG mode) and the proper wiring connected See (port2.doc) click on the BEGIN button. The Bytes transferred window will start counting and READ will display on the indicator. The program has been successfully loaded.

NUM 2 3 1:19 PM

An error message may appear if the indicator is not in idle mode, the wrong com port is selected, the baud rates and data formats on the PC and port2 on the indicator do not match or improper wiring.

_ 8 ×



| Reset Configuration parameters to factory defaults. | | | | | |
|---|---------|-------------------------|-------------------------|--|--|
| 🏦 Start 🛛 📶 💭 🏈 🗐 🔍 🐨 | EZ Link | Document1 - Microsoft W | 🛛 🔮 🕅 📶 😂 🎱 🚴 1:29 PM 🗌 | | |

| 🚍 EZ Link | |
|-------------------------------------|--|
| <u>File U</u> tilities <u>H</u> elp | |
| | |

| Port | Com 1 O Com 2 | O Com 3 O Co | om 4 |
|--|--|-----------------------------------|---|
| Baud Rate 110 300 600 1200 2400 4800 9600 | Parity © None © Even © Odd © Space © Mark | Data Bits C 7 Bits C 8 Bits | Stop Bits © 1 © 1.5 © 2 Default |
| C 14400 C 19200 C 38400 | ОК | Cancel | Help |

_ 8 ×

| | | | Com Err 0 | | NUM |
|---------------------------|---------|----------------------------------|-----------|-----------|-----------|
| 🎉 Start 🛛 📶 🍘 🍏 🗐 🚇 🧐 🚺 🕅 | EZ Link | Document1 - Microsoft W 🔍 C:\BC5 | | 🏵 🖼 📶 🚵 🗳 | 🚵 1:35 PM |

Connect a cable between the indicator and the PC. Use the following diagram for signal connections. NOTE: There are 2 types of PC communications port connectors; 25pin female (left hand diagram) and 9pin female (right hand diagram).





Select the correct com port 1, 2, 3 or 4. Select 9600 baud rate, Parity none, Data bits 8, Stop bits 1. Click OK and save to disk. These settings will be loaded when Ezlink is launched and will not affect any other settings. Settings are restored when Ezlink is closed. Retry uploading the program.

NOTE: No other program can be running on the computer that uses the same serial port com port while trying to upload or download files to or from the indicator. Like Hyperterminal, Procomm, wedge or any other serial communications software or and error will occur.

Contact the factory for technical support if needed. (714) 921-1353